

Other Environmental Reports

Soil Decontamination

In the independent soil contamination research conducted in 2002, contaminated soil was found in a part of the Head Office site. We reported this situation to the relevant authority (Matsudo municipal government) and started decontamination work.

In 2004, we investigated whether there was any soil contamination at the site of our subsidiary, Mabuchi Precision Industries, Ltd., upon the closure of the factory and detected soil contamination. We immediately reported this situation to the Gunma prefectural government and started decontamination work.

Decontamination of areas having a high level of contamination at the above two locations has already been completed, but decontamination of areas with a low level of contamination is still continuing. We are trying various measures to complete decontamination at an early date.

In 2010, all measured values showed an improvement as a result of decontamination work. Therefore, we judged the current decontamination method to be effective and decided to use it continuously.

The decontamination results in 2010 and the future policy were reported to the Matsudo municipal and Gunma prefectural governments and their approvals were obtained. We will continue our decontamination work steadily.




Soil decontamination equipment installed in the premises of the Head Office


Report of Environmental Data

The following tables show the environmental data of the Mabuchi Group: (Data of the Head Office and principal overseas bases are covered.)


Purchased electricity and usage



Coal usage



Water usage



Waste generated

